

PROSTHETIC TIMELINE

HEALING

8 - 12 Weeks

When your incision line is FULLY healed and swelling is stable, the fitting process begins!

FITTING

3 Weeks

Custom cast of your limb is taken, the fit is confirmed and you take final device home.

TRAINING

2 Weeks +

Work with a physical therapist to learn how to walk with your prosthesis. Inpatient/Outpatient.

— **APPROXIMATELY 5 MONTHS** —